

Repair Order Review

RITCHIE IMPL INC COBB

HEADER INFORMATION

Repair Order #	Date	Time	Tag #		
134619C	09/06/2019	0804	8540C		
Srvc Writer	Cust #	MOP	Stock #	Vin/Serial #	Unit Description
001071	63823	CAS	8540C	49404205	2013 CS 970 FH
RO Note			Meter In	Meter Out	Promise Date
			2549.000	0.000	

CUSTOMER INFO

Purchase Order # : 1

Bill To :

Name : SHARPE HOLDINGS INC.  
 Address : 6417 SHELBY CR 150  
 Address 2 : SUITE A  
 City : BETHEL  
 State : MO  
 Zip : 63434  
 Phone : 6602846212  
 Fax :  
 Cell :

Ship To :

Ship Name :  
 Ship Address :  
 Ship Address 2 :  
 Ship City :  
 Ship State :  
 Ship Zip :  
 Ship Phone :  
 Ship Fax :  
 Ship Cell :  
 Ship Contact :  
 Ship Via :

INVOICE INFORMATION

Misc Charge Settings : 1  
 Misc Override Charge : 0

CONDITION INFORMATION

Cond	Type	Description	Labor	Parts
001		MAIN DRIVE BELT	487.50	1583.93
Sublet	Other	Total		
0.00	0.00	2071.43		

CONDITION NOTES

Description :

Cause :

Fix :

9/6/2019  
 2549 ENGINE /2050 CYLINDER HOURS

1. REMOVE LEFT FRONT TIRE ; INSPECT IDLER BEARING - OK; REMOVE AND REPLACE MAIN DRIVE BELT
2. RUN MACHINE , INSPECT OPERATION - OK

GENERAL INFORMATION

## Repair Order Review

RITCHIE IMPL INC COBB

Parts Price Code : 2      Parts Sales Code : 04      Parts Tax Code : 00  
 Parts Discount : 0      Part Sales History :  
 Date Opened : 09/06/2019      Date Close: 09/17/2019      Suppress Labor : Y  
 Component Serial # :  
 Component Description :

### BILLING INFO

Max Billing : 0.00      Min Billing : 0.00  
 Disc % Labor : 0      Disc % Labor : 0

### OPCODES

Opcode : L1      Description : DON  
 Rate Code :      Tax Code : 00      Sales Code : 55  
 Flat Rate Hours : 0.000      Bill Hours : 3.750      Fixed Amount : 0.00      Amount : 487.50  
 Long Description :  
 LABOR

Tech and ID	Date	In	Out	Hours	LT	Description	SRC	F	Mod Date	ModTm
DONALD D. SADLER	09/06/2019	12.001	15.000	3.000	R	DON	TSE	A	09/08/2019	11.900
DONALD D. SADLER	09/08/2019	14.750	15.500	0.750	R	DON	TSE	U	09/09/2019	05.717
DONALD D. SADLER	BillAdjust			0.750		DON				

### PARTS

Parts Salesman: MP      Price Code: 2      Tax Code: 00      Sales Code: 04      Discount: 0

Part	Ven	Typ	Description	Ship QTY	BO QTY	Bin Location	Unit Price	Ext Price	Disc	PC	Tax	SC
1319991	297	1		1	0		1059.69	1551.11	0	2	00	04
2160900	297	1	BEARING GR	2	0	2E11E	9.85	16.41	0	2	00	04

### TOTAL

	Labor	Parts	Sublet	Other	Total
Customer Totals	487.50	1583.93	0.00	0.00	2071.43

Repair Order Review

RITCHIE IMPL INC COBB

HEADER INFORMATION

Repair Order #	Date	Time	Tag #		
134344C	08/10/2019	1749	8540C		
Srvc Writer	Cust #	MOP	Stock #	Vin/Serial #	Unit Description
000730	63823	AR	8540C	49404205	2013 CS 970 FH
RO Note			Meter In	Meter Out	Promise Date
			2390.000	0.000	

CUSTOMER INFO

Purchase Order # : 970 CHOPPER #4205

Bill To :

Name : SHARPE HOLDINGS INC.  
 Address : 6417 SHELBY CR 150  
 Address 2 : SUITE A  
 City : BETHEL  
 State : MO  
 Zip : 63434  
 Phone : 6602846212  
 Fax :  
 Cell :

Ship To :

Ship Name :  
 Ship Address :  
 Ship Address 2 :  
 Ship City :  
 Ship State :  
 Ship Zip :  
 Ship Phone :  
 Ship Fax :  
 Ship Cell :  
 Ship Contact :  
 Ship Via :

INVOICE INFORMATION

Misc Charge Settings : 1  
 Misc Override Charge : 0

CONDITION INFORMATION

Cond	Type	Description	Labor	Parts
001		RAN SOMETHING THROUGH THE	7311.20	24129.69
Sublet	Other	Total		
0.00	837.50	32278.39		

CONDITION NOTES

Description :  
 CHOPPER. INSPECT FOR DAMAGE AND REPAIR AS NEEDED.

Cause :

Fix :  
 8/14/2019  
 2390 ENGINE/1934 CYLINDER HOURS  
 1. REMOVE CYLINDER KNIVES ; INGESTION AT CENTER OF DRUM, BROKE OUT CENTER OF KNIVES ON LEFT SIDE, BENT LEFT SIDE KNIFE MOUNT; WENT THROUGH ACCELERATOR, BENT MOUNTING SURFACES  
 2. REMOVE DRIVE TIRES, REMOVE CYLINDER HOUSING ASSEMBLY  
 3. LIFT OUT CYLINDER ASSEMBLY, CUT OFF BEARINGS , REMOVE LEFT SIDE DRIVE SHAFT  
 4. INSTALL LEFT CENTER WEB, WAITING ON OUTSIDE WEB  
 5. REMOVE ACCELERATOR ASSEMBLY AND ACCELERATOR HOUSING

## Repair Order Review

RITCHIE IMPL INC COBB

6. REINSTALL HOUSING, SET IN PLACE, REPLACE ANGLE LINER AT BOTTOM OF TOWER LINER  
S

7. INSTALL ACCELERATOR ASSEMBLY, INSTALL NEW BEARINGS AND SEALS; FILLED BOTH BEARINGS WITH GREASE AFTER ASSEMBLY

8. INSTALL DRIVE PULLEY - TORQUE

9. CENTER ACCELERATOR, LOCK IN PLACE

10. JON INSTALL BACK PLATE AND PADDLES

960

1. TROUBLESHOOT ELECTRICAL FOR CONTOUR ASSEMBLY; POWER TO Y151 FAULTY

2. REMOVE LEFT SIDE FENDER CONNECTION, CLEAN CONNECTION VERIFIED OPERATION

3. CONTOUR NOT FUNCTIONING CORRECTLY; HYDRAULIC HOSES TO FENDER CONNECTION BACKWARDS, SWITCHED AND VERIFIED OPERATION - OK

8/15

1. ASSEMBLE RIGHT CYLINDER BEARING AND SEALS

2. INSTALL NEW BEARING IN STATIONARY KP IDLER ON FRAME

3. INSTALL KP, ALIGN TOP DRIVE PULLEY AND TORQUE

4. OPEN SPOUT LINER, INSPECT FOR DEBRIS - OK

5. REPLACE LEFT SIDE LINER, TOP LONG LINER, FIRST LINER IN ARCH

6. ASSEMBLE CYLINDER; INSTALL TWO NEW WEBS ON LEFT SIDE, TORQUE HARDWARE

7. ASSEMBLE CYLINDER INTO HOUSING, INSTALL BEARING HOUSINGS, BACK COVER, TORQUE HOUSINGS

8. SET BEARING PRELOAD, INSTALL SEAL ON RIGHT SIDE

9. HEAT PULLEY SPACER AND INSTALL ON LEFT SHAFT

10. INSTALL BOTH DRIVE PULLEYS AND TORQUE

960

DEFLECTOR COMING DOWN ON ITS OWN

1. REMOVE AND REPLACE Y584 SOLENOID VALVE, VERIFIED OPERATION - OK

8/16

1. INSTALL CYLINDER HOUSING ASSEMBLY INTO MACHINE, REATTACH CYLINDERS AND PINS  
REINSTALL ALL HYDRAULIC HOSES, AND ELECTRICAL

2. RUN MACHINE, JON INSTALLED ALL SHIELDING, TIRES, TORQUE WHEELS

3. INSTALL SHEAR BAR ANVIL (THEY MILLED) TORQUE ALL HARDWARE

4. INSTALLED NEW SHEAR BAR, TORQUE

5. INSTALL NEW KNIVES, ADJUST AND TORQUE

6. ADJUST STONE, RESET COUNTER

7. RUN SHARPENER AND SHEAR BAR OPERATION - OK

8. HOOKED UP CORN HEAD TROUBLESHOOT ELECTRICAL FOR CONTOUR OPERATION, REPLACED HARNESS FROM FENDER TO SOLENOIDS/MODULE; LEARNED UPPER AND LOWER LIMITS, VERIFIED OPERATION - OK

## GENERAL INFORMATION

Parts Price Code : 2

Parts Sales Code : 04

Parts Tax Code : 00

Parts Discount : 0

Part Sales History :

Date Opened : 08/10/2019

Date Close: 09/06/2019

Suppress Labor : Y

Component Serial # :

Component Description :

## Repair Order Review

RITCHIE IMPL INC COBB

### BILLING INFO

Max Billing : 0.00    Min Billing : 0.00  
 Disc % Labor : 0    Disc % Labor : 0

### OPCODES

Opcode : L1                      Description : LABOR  
 Rate Code :                      Tax Code : 00                      Sales Code : 55  
 Flat Rate Hours : 0.000        Bill Hours : 56.240                Fixed Amount : 0.00                Amount : 7311.20  
 Long Description :  
     DON

Tech and ID	Date	In	Out	Hours	LT	Description	SRC	F	Mod Date	ModTm
DONALD D. SADLER	08/13/2019	15.001	21.500	6.500	R	LABOR	TSE	A	08/13/2019	22.533
DONALD D. SADLER	08/14/2019	06.000	23.250	17.250	R	LABOR	TSE	U	08/14/2019	23.567
DONALD D. SADLER	08/15/2019	06.000	18.000	12.000	R	LABOR	TSE	U	08/16/2019	01.317
DONALD D. SADLER	08/15/2019	18.001	23.990	5.990	R	LABOR	TSE	A	08/16/2019	01.333
DONALD D. SADLER	08/16/2019	00.000	01.150	1.150	R	LABOR	TSE	A	08/16/2019	01.333
DONALD D. SADLER	08/15/2019	19.500	23.990	4.490	R	LABOR	TSE	U	08/16/2019	06.867
DONALD D. SADLER	08/15/2019	18.001	23.990	5.990	R	LABOR	TSE	D	08/16/2019	06.867
DONALD D. SADLER	08/16/2019	06.300	19.100	12.800	R	LABOR	TSE	A	08/17/2019	06.867
DONALD D. SADLER	08/19/2019	06.750	08.800	2.050	R	LABOR	TSE	A	08/19/2019	08.750
DONALD D. SADLER	BillAdjust			33.740		LABOR				

### PARTS

Parts Salesman: 98    Price Code: 2    Tax Code: 00    Sales Code: 04    Discount: 0

Part	Ven	Typ	Description	Ship QTY	BO QTY	Bin Location	Unit Price	Ext Price	Disc	PC	Tax	SC
FREIGHTOUT	965	1	FREIGHTOUT	1	0	OFFICE	0.00	59.53	0	2	00	04
17995400	297	1	VALVE AM	1	0	4C04C	346.12	521.76	0	2	00	04
FREIGHTIN	965	1	FREIGHT IN	1	0	OFFICE	0.00	155.83	0	2	00	04
FREIGHTIN	965	1	FREIGHT IN	1	0	OFFICE	0.00	94.58	0	2	00	04
2417931	297	1	EP3 GREASE	48	0	HWF04	3.41	5.68	0	2	00	04
0773821	297	1	FILTER,SAF	4	0	SP201C	94.86	138.85	0	2	00	04
0773672	297	1	FILTER ELE	4	0	SP302	110.79	162.17	0	2	00	04
1268410	297	1	SAFETY CAR	2	0	SP203C	92.69	135.68	0	2	00	04
24022700	297	1	AIR CLEANE	2	0	SP201A	123.39	180.61	0	2	00	04
1442310	297	1	CHANGEABLE	8	0	3B	66.61	111.02	0	2	00	04
5596460	297	1	POCKET FIL	4	0	SP201A	41.19	68.66	0	2	00	04
FREIGHTIN	965	1	FREIGHT IN	1	0	OFFICE	0.00	49.24	0	2	00	04
9874043	297	1	COVER PLAT	1	0	SP402E	272.19	410.31	0	2	00	04
13185770	297	1	WASHER	1	0		1765.48	2452.06	0	2	00	04
2356662	297	1	PIN,TENSIO	2	0	2E05C	0.41	0.77	0	2	00	04
1447310	297	1	GASKET	1	0	3E02A	35.33	58.88	0	2	00	04
1445204	297	1	ACCELERATO	1	0	NBG2	1975.35	2948.28	0	2	00	04
1301521	297	1	RETAINER	4	0		40.26	67.10	0	2	00	04
1230730	297	1	WEAR PLATE	2	0		190.14	278.32	0	2	00	04
1301793	297	1	HOUSING	1	0	NBB3	1495.16	2231.58	0	2	00	04
26093010	297	1	WASHER	1	0	2D07D	16.07	26.78	0	2	00	04
2126390	297	1	ORING	1	0	2C10A	9.16	15.26	0	2	00	04
26069801	297	1	SPHERICAL	1	0	4C03C	159.02	232.77	0	2	00	04

## Repair Order Review

### RITCHIE IMPL INC COBB

8085760	297	1	SHIM	2	0	2C12C	4.57	7.62	0	2	00	04
8085690	297	1	SHIM	1	0	2C12E	4.73	7.88	0	2	00	04
26225030	297	1	WASHER	1	0		16.07	26.78	0	2	00	04
26225020	297	1	WASHER	1	0		16.07	26.78	0	2	00	04
26180680	297	1	SPHERICAL	1	0	4C05B	159.94	234.12	0	2	00	04
2142070	297	1	ORING	1	0	2C07B	9.31	15.51	0	2	00	04
2342520	297	1	ROTARY SHA	2	0	3B07C	28.43	47.39	0	2	00	04
26199280	297	1	BACK-UP RI	1	0		49.13	84.33	0	2	00	04
2430650	297	1	CIRCLIP	1	0	2C10C	7.89	13.14	0	2	00	04
26200931	297	1	WASHER	1	0	2D07D	15.75	27.04	0	2	00	04
13901551	297	1	SPACER RIN	1	0		134.29	202.44	0	2	00	04
9847432	297	1	TAPERED RI	2	0	2F10E	44.40	76.21	0	2	00	04
2336990	297	1	WASHER/TEN	2	0	2C08D	3.92	6.53	0	2	00	04
2181720	297	1	BOLT	2	0	2F02E	5.77	9.61	0	2	00	04
2198130	297	1	HEX.NUT	10	0	2F07C	1.37	2.59	0	2	00	04
2198140	297	1	HEX.HEAD B	10	0	2F03H	7.37	12.28	0	2	00	04
13185790	297	1	WASHER	1	0		1601.26	2223.97	0	2	00	04
ZPX80050	198	1	CLEAR RTV	1	0	CARTC02	5.03	7.40	0	2	01	03
4973522	297	1	CABLE HARN	1	0	13H02A	513.67	751.89	0	2	00	04
13187381	297	1	FORM PIECE	4	0	OLD	6.33	9.71	0	2	00	04
13189151	297	1	FORM PIECE	4	0	1D04C	5.82	9.71	0	2	00	04
2335510	297	1	NUT	2	0	2F07B	1.92	3.58	0	2	00	04
ZPX24310	198	1	BLUE LOCKT	1	0	CARTC02	11.05	16.25	0	2	01	03
2355910	297	1	BOLT	4	0	2F02C	3.26	6.15	0	2	00	04
2110840	297	1	WASHER/BEV	4	0	2F05C	2.24	4.23	0	2	00	04
2387860	297	1	WASHER	1	0	2F05E	0.99	1.87	0	2	00	04
2393941	297	1	WASHER/CON	2	0	HWA02A	0.34	0.64	0	2	00	04
07485	800	1	3u0022DISC	5	0	SERVICE	2.70	6.42	0	2	00	04
				0	0		0.00	0.00	0		00	
1303140	297	1	COACH BOLT	6	0	HWA01E	3.35	6.31	0	2	00	04
1417970	297	1	LINER	1	0	LR1	150.00	202.00	0	2	00	04
1417961	297	1	WEAR PLATE	1	0	LR5	135.94	183.07	0	2	00	04
1417743	297	1	WEAR PLATE	1	0	LR6	117.19	157.81	0	2	00	04
0766314	297	1	COVER	1	0	SP202B	74.06	113.56	0	2	00	04
14101721	297	1	L/H KNIFE	5	0	TILL2	153.05	224.03	0	2	00	04
14101731	297	1	R/H KNIFE	5	0	OLD	153.05	224.03	0	2	00	04
13180191	297	1	SHEARBAR	1	0	3E01	745.20	1045.35	0	2	00	04
13244381	297	1	LEDGE	1	0	3D10	349.92	512.20	0	2	00	04
2428241	297	1	CIRCLIP	4	0	2F05A	0.06	0.12	0	2	00	04
2383170	297	1	BOLT	4	0	2F03G	1.01	1.91	0	2	00	04
2382810	297	1	RETAINER	1	0	2F06B	3.41	6.42	0	2	00	04
2351900	297	1	CIRCLIP	2	0	2D04H	3.13	5.89	0	2	00	04
2379610	297	1	BEARING SE	2	0	4B08G	8.14	13.56	0	2	00	04
9630045	297	1	ADJUSTING	2	0	4B08G	2.96	5.58	0	2	00	04
2440310	297	1	BEARING GR	1	0	4E04B	26.36	43.93	0	2	00	04
2435380	297	1	BEARING -	1	0	4F03C	56.86	94.77	0	2	00	04
8/15				0	0		0.00	0.00	0		00	
1405530	297	1	SCREW	4	0	1C04C	12.87	21.45	0	2	00	04
1238521	297	1	ANTIFRICTI	4	0	1C03C	5.40	9.00	0	2	00	04
2351940	297	1	CIRCLIP	2	0	2D04H	6.27	10.45	0	2	00	04
1445400	297	1	HOUSING	1	0	5E07	209.37	315.63	0	2	00	04
2393931	297	1	WASHER/CON	24	0	HWA02A	0.12	0.23	0	2	00	04

## Repair Order Review

### RITCHIE IMPL INC COBB

2361700	297	1	NUT 8MM	24	0	HWA02C	0.10	0.18	0	2	00	04
2339820	297	1	BOLT/SUNK	22	0	HWA01B	0.77	1.46	0	2	00	04
0677973	297	1	LEDGE	1	0	CLRACK2	35.16	53.91	0	2	00	04
2393941	297	1	WASHER/CON	15	0	HWA02A	0.34	0.64	0	2	00	04
2361710	297	1	NUT 10MM	15	0	HWA02D	0.12	0.22	0	2	00	04
5025110	297	1	BOLT	15	0	HWA01C	1.39	2.61	0	2	00	04
2393890	297	1	WASHER/CON	2	0	HWA02B	0.28	0.53	0	2	00	04
1405221	297	1	GLIDE RAIL	2	0	1C03C	2.99	5.63	0	2	00	04
1437920	297	1	BEARING UN	1	0	4C05B	346.21	506.77	0	2	00	04
2436330	297	1	ROLLER BEA	1	0	1E03C	137.29	200.96	0	2	00	04
2141320	297	1	SHAFT SEAL	1	0	1E03C	36.49	60.81	0	2	00	04
1445380	297	1	RING	1	0	1E03C	61.04	101.73	0	2	00	04
6440190	297	1	TAPERED RI	2	0	2C02H	21.09	36.20	0	2	00	04
2151900	297	1	BOLT/HEX	1	0	2F02B	3.07	5.79	0	2	00	04
2393910	297	1	WASHER/16M	8	0	HWA02B	0.67	1.26	0	2	00	04

### OTHER

Code : BTM      Description : TRIP CHARGE MILEAGE      Tax Code : 00  
 Cost : 1.25      Qty : 670      Amount :

	TOTAL				
	Labor	Parts	Sublet	Other	Total
Customer Totals	7311.20	24129.69	0.00	837.50	32278.39

Repair Order Review

RITCHIE IMPL INC COBB

HEADER INFORMATION

Repair Order #	Date	Time	Tag #		
134157C	07/27/2019	0741	8540C		
Srvc Writer	Cust #	MOP	Stock #	Vin/Serial #	Unit Description
000730	63823	CAS	8540C	49404205	2013 CS 970 FH
RO Note			Meter In	Meter Out	Promise Date
			2340.000	0.000	

CUSTOMER INFO

Purchase Order # : 970 #4205

Bill To :

Name : SHARPE HOLDINGS INC.  
 Address : 6417 SHELBY CR 150  
 Address 2 : SUITE A  
 City : BETHEL  
 State : MO  
 Zip : 63434  
 Phone : 6602846212  
 Fax :  
 Cell :

Ship To :

Ship Name :  
 Ship Address :  
 Ship Address 2 :  
 Ship City :  
 Ship State :  
 Ship Zip :  
 Ship Phone :  
 Ship Fax :  
 Ship Cell :  
 Ship Contact :  
 Ship Via :

INVOICE INFORMATION

Misc Charge Settings : 1  
 Misc Override Charge : 0

CONDITION INFORMATION

Cond	Type	Description	Labor	Parts
001		GET MACHINE READY FOR CORN	2204.80	4314.67
Sublet	Other	Total		
0.00	250.00	6769.47		

CONDITION NOTES

Description :

Cause :

Fix :

7/31/2019  
 2340 ENGINE/1896 CYLINDER HOURS

1. OPEN FEED ROLLS, INSPECT
2. REMOVE AND REPLACE CAST LEDGE, TORQUE BOLTS, TORQUE ANVIL BOLTS
3. REMOVE , CLEAN, TURN SHEAR BAR; TORQUE BOLTS
4. REMOVE KNIVES, CLEAN CYLINDER KNIFE MOUNTING AREA
5. INSTALL, ADJUST AND TORQUE KNIVES
6. STONE HOLDER STUCK; HEAT, WORK BACK AND FORTH TO FREE UP; REMOVE ASSEMBLY, CLEAN ALL THREADS- REINSTALL AND ADJUST



## Repair Order Review

RITCHIE IMPL INC COBB

7. SHARPEN KNIVES -RUN SHEAR BAR OPERATION - OK
  8. REMOVE, CLEAN SMOOTH ROLL; INSTALL NEW SCRAPER, INSTALL AND ADJUST
  9. GREASE TOP FEED ROLL DRIVE LINE, GREASE FEED ROLL DIVE LINE
  10. CHANGE OIL IN RIGHT SIDE FEED ROLL GEAR BOX
  11. TOP OFF HYDRAULIC OIL LEVEL
  12. FILL AUTO-LUBE CONTAINER
  13. INSPECT SPOUT, REPLACE ONE BOLT ON LEFT SIDE ( HEAD WORE OFF )
  12. GREASE KP STATIONARY IDLER AND INSPECT TENSIONER PULLEY - OK
  13. REPLACE ONE GREASE FITTING ON RIGHT SIDE FEED ROLL CONTROL ARM AND ONE ON THE LEFT
  14. REMOVE AND REPLACE HEADER DRIVE BELT
  15. CHECKED FAULT CODES WITH CDS; NO CURRENT CODES THAT RELATE TO OPM CONTROL MODULE FAILURE. DELETE ERRORS.INSPECT HARNESS BY FUSE PANEL. CUSTOMER WILL MONITOR , POSSIBLE CAN BUS ISSUE
- 8/4
1. DRIVE TIME BACK

### GENERAL INFORMATION

Parts Price Code : 2      Parts Sales Code : 04      Parts Tax Code : 00  
 Parts Discount : 0      Part Sales History :  
 Date Opened : 07/27/2019      Date Close: 08/08/2019      Suppress Labor : Y  
 Component Serial # :  
 Component Description :

### BILLING INFO

Max Billing : 0.00      Min Billing : 0.00  
 Disc % Labor : 0      Disc % Labor : 0

### OPCODES

Opcode : L1      Description : LABOR  
 Rate Code :      Tax Code : 00      Sales Code : 55  
 Flat Rate Hours : 0.000      Bill Hours : 16.960      Fixed Amount : 0.00      Amount : 2204.80  
 Long Description :  
 DON

Tech and ID	Date	In	Out	Hours	LT	Description	SRC	F	Mod Date	ModTm
DONALD D. SADLER	07/30/2019	18.251	20.500	2.250	R	LABOR	TSE	A	07/30/2019	22.083
DONALD D. SADLER	07/31/2019	06.000	14.983	8.980	R	LABOR	TTE	A	07/31/2019	14.983
DONALD D. SADLER	07/31/2019	14.984	15.500	0.520	R	LABOR	TSE	U	07/31/2019	15.983
DONALD D. SADLER	07/31/2019	14.984	15.967	0.980	R	LABOR	TSE	U	07/31/2019	20.850
DONALD D. SADLER	07/31/2019	14.984	15.500	0.520	R	LABOR	TSE	D	07/31/2019	20.850
DONALD D. SADLER	07/27/2019	10.001	11.100	1.100	R	LABOR	TSE	A	08/02/2019	09.467
DONALD D. SADLER	08/04/2019	15.001	17.650	2.650	R	LABOR	TSE	A	08/04/2019	13.067
DONALD D. SADLER	08/05/2019	7.551	08.550	1.000	R	LABOR	TSE	A	08/05/2019	09.400
DONALD D. SADLER	08/03/2019	15.001	17.650	2.650	R	LABOR	TSE	A	08/06/2019	17.367
DONALD D. SADLER	08/04/2019	15.001	17.650	2.650	R	LABOR	TSE	D	08/06/2019	17.367
DONALD D. SADLER	BillAdjust			1.500		LABOR				

## Repair Order Review

RITCHIE IMPL INC COBB

### PARTS

Parts Salesman: 98    Price Code: 2    Tax Code: 00    Sales Code: 04    Discount: 0

Part	Ven	Typ	Description	Ship QTY	BO QTY	Bin Location	Unit Price	Ext Price	Disc	PC	Tax	SC
2147371	297	1	BOLT HEXAG	1	0	2F02E	9.74	16.24	0	2	00	04
9847072	297	1	SEAL/WEDGE	2	0	2F08G	6.17	10.28	0	2	00	04
2417931	297	1	EP3 GREASE	24	0	HWF04	3.41	5.68	0	2	00	04
13124424	297	1	GRINDSTONE	1	0	4D05	71.44	104.57	0	2	00	04
14101731	297	1	R/H KNIFE	5	0	OLD	153.05	224.03	0	2	00	04
14101721	297	1	L/H KNIFE	5	0	TILL2	153.05	224.03	0	2	00	04
13189151	297	1	FORM PIECE	20	0	1D04C	5.82	9.71	0	2	00	04
13187381	297	1	FORM PIECE	20	0	OLD	6.33	9.71	0	2	00	04
1474450	297	1	HVLP 46 AG	1	0	NAW3C	60.86	93.32	0	2	00	04
9902271	297	1	ANGLE,FITT	1	0	2C05A	12.87	21.45	0	2	00	04
9902281	297	1	UNION/STRA	1	0	2C05A	6.58	10.97	0	2	00	04
1303140	297	1	COACH BOLT	1	0	HWA01E	3.35	6.31	0	2	00	04
13242220	297	1	POWER BAND	1	0	3G04	107.81	145.19	0	2	00	04
1474370	297	1	EP2 GREASE	1	0	HWF03	2.95	5.12	0	2	00	04
2350910	297	1	PIN	1	0	2F06H	0.06	0.12	0	2	00	04
13188332	297	1	STRIPPER B	1	0	4C09	411.83	602.82	0	2	00	04
2110840	297	1	WASHER/BEV	1	0	2F05C	2.24	4.23	0	2	00	04
7/31				0	0		0.00	0.00	0		00	
2428241	297	1	CIRCLIP	4	0	2F05A	0.06	0.12	0	2	00	04
				0	0		0.00	0.00	0		00	
2383170	297	1	BOLT	4	0	2F03G	1.01	1.91	0	2	00	04
2335140	297	1	SCREW SOCK	4	0	2F03B	0.99	1.86	0	2	00	04
13903510	297	1	LEDGE	1	0	5F07	343.76	503.19	0	2	00	04

### OTHER

Code : BTM    Description : TRIP CHARGE MILEAGE    Tax Code : 00  
 Cost : 1.25    Qty : 200    Amount :

TOTAL					
	Labor	Parts	Sublet	Other	Total
Customer Totals	2204.80	4314.67	0.00	250.00	6769.47

Repair Order Review

RITCHIE IMPL INC COBB

HEADER INFORMATION

Repair Order #	Date	Time	Tag #		
131864C	12/01/2018	0718	8540C		
Srvc Writer	Cust #	MOP	Stock #	Vin/Serial #	Unit Description
000730	63823	CAS	8540C	49404205	2013 CS 970 FH
RO Note			Meter In	Meter Out	Promise Date
			2198.000	0.000	

CUSTOMER INFO

Purchase Order # : 970 #4205 CHOPPER

Bill To :

Name : SHARPE HOLDINGS INC.  
 Address : 6417 SHELBY CR 150  
 Address 2 : SUITE A  
 City : BETHEL  
 State : MO  
 Zip : 63434  
 Phone : 6602846212  
 Fax :  
 Cell :

Ship To :

Ship Name :  
 Ship Address :  
 Ship Address 2 :  
 Ship City :  
 Ship State :  
 Ship Zip :  
 Ship Phone :  
 Ship Fax :  
 Ship Cell :  
 Ship Contact :  
 Ship Via :

INVOICE INFORMATION

Misc Charge Settings : 1  
 Misc Override Charge : 0

CONDITION INFORMATION

Cond	Type	Description	Labor	Parts
001		WINTER SERVICE INSPECTION	13120.90	26170.17
Sublet	Other	Total		
162.50	-1742.11	37711.46		

CONDITION NOTES

Description :

Cause :

Fix :

2199 ENGINE/1785 CYLINDER HOURS

12/6/2018

1. OPEN FEED ROLLS AND COVERS, INSPECT MACHINE
2. WASH
3. TROUBLESHOOT ELECTRICAL FOR ACCELERATOR ADJUSTER; ADJUSTER MOTOR BAD
4. REMOVE ACCELERATOR BACK PLATE, INSPECT ACCELERATOR; CONCERN OF MOVEMENT AT RIGHT SIDE OF ACCELERATOR BY WELD; COULD BE CAUSING VIBRATION
5. REMOVE CUTTING CYLINDER ASSEMBLY FROM MACHINE

## Repair Order Review

RITCHIE IMPL INC COBB

6. DISASSEMBLE MAIN DRIVE CLUTCH, DISC LOOKS TO BE SLIPPING; WILL DISCUSS OPTION  
S

7. FLUSH WATER TANK APPLICATOR WITH RV ANTI-FREEZE, FLUSH REAR WATER TANK WITH R  
V ANTI-FREEZE, VERIFIED OUT BOTH PUMPS

12/10

1. DISASSEMBLE CUTTING CYLINDER, SHAFTS HAD GROOVES WORE IN FROM SEAL; WILL PROC  
EED WITH REPLACING CUTTING CYLINDER BEARINGS WITH COMPLETE KIT

2. DISASSEMBLE ACCELERATOR

3. DISASSEMBLE HYDRAULIC FEED ROLL DRIVE PUMP MOTOR, SPLINE EXTREMELY WORN

4. REMOVE AND REPLACE PUMP DRIVE WITH NEW BEARINGS

12/11

1. DISASSEMBLE CUTTING CYLINDER, CLEAN

2. ASSEMBLE CUTTING CYLINDER WITH NEW UPDATE KIT; ALL NEW SEALS, NEW SHAFTS AND  
NEW BEARINGS

12/12

1. INSTALL DRIVE PULLEY HUB, TORQUE, INSTALL PULLEY

2. INSTALL SHARPENER DOOR, HYDRAULIC CYLINDER

3. ADJUST SHARPENER STONE, ADJUST DRUM BOTTOM

4. REMOVE ACCELERATOR

5. REMOVE AND REPLACE TOWER LINERS, LEDGE, AND ACCELERATOR SIDE LINERS

6. INSTALL NEW ACCELERATOR, INSTALL NEW GLIDES, NEW BEARING ASSEMBLIES

12/13

1. ALIGN ACCELERATOR TORQUE IN PLACE

2. REINSTALL PULLEYS, TORQUE

3. CLEAN, INSTALL MAD JAG PADDLES

4. REMOVE AND REPLACE BEARINGS IN MAIN DRIVE BELT TENSIONER PULLEY AND GROOVED P  
ULLEY UNDERNEATH

5. INSTALL HYDRAULIC DRIVE PUMP, HOOK UP ALL HYDRAULIC LINES

6. INSTALL NEW GREASE PUMP IN AUTO LUBE (CAME WITH CYLINDER KIT)

7. INSTALL TEE FIT IN CYLINDER LUBE BANK

12/14

1. CHANGE OIL IN BOTH FRONT FINAL DRIVES, CENTER TRANSMISSION, REAR AXLE, BOTH R  
EAR PLANETARY, ENGINE ACCESSORY, ENGINE FAN, AND FEED ROLL DRIVE GEAR BOX

2. REPLACE OIL COOLER HOSES FROM HYDRO AND HEADER VALVE, REPLACED COOLER HOSE ON  
OIL COOLER STEEL LINE AT CENTER OF CHOPPER BACK TO COOLER (4 TOTAL)

3. CHANGED HYDRAULIC FILTER, FILLED SYSTEM WITH OIL

4. REASSEMBLE MAIN DRIVE AND CLUTCH ASSEMBLY

12/17

1. REMOVE AND REPLACE LEFT SIDE SPOUT LINER, TOP LONG LINER

2. INSTALL MAD JAG TRANSITION CHUTE LINER, ALIGN AND INSTALL SIDE LINERS

3. FREE UP LEFT SIDE CYLINDER PIN, CLEAN UP PIN, CLEAN PIN BORE, REASSEMBLE AND  
VERIFIED IT WOULD TAKE GREASE

4. RIGHT SIDE PIN, STUCK SOLID, CUT PIN OFF

12/18

1. PRESS OUT PIN, CLEAN CYLINDER BORE, REINSTALL CYLINDER, ORDER PIN

2. INSTALL CUTTING CYLINDER ASSEMBLY, HOOK UP ALL LINES AND ELECTRICAL

3. PUSH GREASE THROUGH CYLINDER BEARINGS, RUN CYLINDER, CHECK OPERATION, OK

4. INSTALL LEFT SIDE SHIELDING, INSTALL LEFT TIRE, TORQUED BOTH WHEELS

5. GREASE FEED ROLL DRIVE LINE

6. GREASE FEED ROLL DRIVE SHAFT ACROSS TOP OF FEED ROLLS

Repair Order Review

RITCHIE IMPL INC COBB

7. REBUILD TRANSITION CHUTE HYDRAULIC CYLINDER, INSTALL
8. CHANGE HYDRAULIC OIL IN FEED ROLL GEAR BOXES; LEFT AND RIGHT SIDE  
12/19
1. REMOVE FEED ROLL SIDE LINERS ABOVE SMOOTH ROLL; TORCHED OFF TO REMOVE; INSTAL  
L NEW
2. REMOVE SHEAR BAR ANVIL, FREE UP PIVOT POINTS, REINSTALL TORQUE HARDWARE
3. REMOVE AND INSTALL NEW SHEAR BAR, TORQUE; NOTE: MAD JAG SHEAR BAR
4. ADJUST ENGINE VALVE LASH
5. REMOVE ENGINE AIR FILTERS, REPLACED INNER FILTERS AND BLEW OUT OUTSIDE ONES
  
6. REMOVE AND REPLACE CAB FILTERS
7. REMOVE AND REPLACE FUEL FILTERS; REPLACED FRONT FILTER BASE ASSEMBLY; SENSOR/  
HARNES WAS DAMAGED
8. VERIFIED SHARPENER AND SHEAR BAR OPERATION - OK
9. CHANGE ENGINE OIL AND FILTERS  
1/2/ 2019
1. INSTALL SHIELDING AROUND SHARPENER
2. INSTALL NEW CYLINDER PIN ON RIGHT SIDE LIFT CYLINDER
3. INSTALL NEW HEADER DRIVE BRAKE AND ADJUST
4. INSTALL NEW HEADER DRIVE BELT
5. INSTALL NEW HAY CHUTE BACK LINER, INSTALL HAY CHUTE
6. REPLACE PLASTIC BUSHINGS FOR ACCELERATOR CONTROL ARM, REINSTALL, CALIBRATE
7. INSTALL NEW ENGINE ACCESSORY DRIVE BELT
8. INSTALL NEW ENGINE FAN BELT
9. CHECK ALL LIGHTS,
  - A. BEACONS; ONE BULB BURNED OUT, ONE MOTOR BAD, REPLACED ONE ASSEMBLY, REPLACED  
ONE BULB
  - B. LEFT RAILING LIGHTS, OUT, REPLACED ONE BULB, FUSED BLOWN FOR INNER ONE
  - C. REPLACED ALL THREE DOOR SWITCHES
  - D. VERIFIED ALL OTHER LIGHTS OPERATIONAL
10. REPLACED REAR DOOR LATCH, ADJUST, VERIFIED ALL LATCHED
11. VACUUM OUT CAB, CLEAN OUT CUBBY COMPARTMENT; MICE PRESENT; PUT REPELLANT IN  
CAB
12. STRAIGHTEN RIGHT SIDE OF REAR BUMPER
13. REMOVE BATTERIES, CLEAN CONNECTIONS, LOAD TEST BOTH BATTERIES-765 CCA-OK; F  
ASTEN BATTERIES IN PLACE, REPLACE POSITIVE CABLE GOING TO INSIDE BATTERY
14. REPLACE PLASTIC COVERS FOR HYDRAULIC OUTLETS ON FRONT FENDER
15. DRAIN ANTI-FREEZE, INSTALL NEW COOLANT
16. WASH UNDER SHIELDING WHERE HYDRAULIC HOSES WERE REPLACED
17. INSTALL ALL SHIELDING, REPLACE FASTENERS AS NECESSARY
18. RINSE OFF REST OF MACHINE
19. TEST METAL ALERT - OK
20. VERIFY AUTO-LUBE WAS GREASING BY REMOVING OUTPUT LINE - OK
21. DRAIN AND REPLACE COOLANT

GENERAL INFORMATION

Parts Price Code : 2      Parts Sales Code : 04      Parts Tax Code : 00  
Parts Discount : 0      Part Sales History :  
Date Opened : 12/01/2018      Date Close: 01/12/2019      Suppress Labor : Y  
Component Serial # :  
Component Description :

## Repair Order Review

RITCHIE IMPL INC COBB

### BILLING INFO

Max Billing : 0.00    Min Billing : 0.00  
 Disc % Labor : 0    Disc % Labor : 0

### OPCODES

Opcode : L1                      Description : LABOR  
 Rate Code :                      Tax Code : 00                      Sales Code : 55  
 Flat Rate Hours : 0.000        Bill Hours : 100.930              Fixed Amount : 0.00              Amount : 13120.90  
 Long Description :  
     DON

Tech and ID	Date	In	Out	Hours	LT	Description	SRC	F	Mod Date	ModTm
DONALD D. SADLER	12/03/2018	12.733	13.050	0.320	R	LABOR	TSE	U	12/05/2018	15.167
DONALD D. SADLER	12/05/2018	13.150	17.233	4.080	R	LABOR	TTE	U	12/05/2018	17.233
DONALD D. SADLER	12/06/2018	06.833	12.200	5.370	R	LABOR	TTE	A	12/06/2018	12.200
DONALD D. SADLER	12/06/2018	06.833	12.200	5.370	R	LABOR	TSE	D	12/06/2018	12.800
DONALD D. SADLER	12/06/2018	06.750	12.200	5.450	R	LABOR	TSE	U	12/06/2018	12.800
DONALD D. SADLER	12/06/2018	12.783	15.800	3.020	R	LABOR	TSE	U	12/06/2018	15.967
DONALD D. SADLER	12/07/2018	15.500	17.000	1.500	R	LABOR	TTE	A	12/07/2018	17.000
DONALD D. SADLER	12/10/2018	06.867	12.183	5.320	R	LABOR	TSE	U	12/10/2018	12.867
DONALD D. SADLER	12/10/2018	12.850	17.050	4.200	R	LABOR	TTE	U	12/10/2018	17.050
DONALD D. SADLER	12/11/2018	10.383	17.333	6.950	R	LABOR	TTE	U	12/11/2018	17.333
DONALD D. SADLER	12/11/2018	10.383	16.600	6.220	R	LABOR	TSE	U	12/11/2018	17.367
DONALD D. SADLER	12/11/2018	10.383	17.333	6.950	R	LABOR	TSE	D	12/11/2018	17.367
DONALD D. SADLER	12/12/2018	06.833	12.150	5.320	R	LABOR	TSE	U	12/12/2018	12.783
DONALD D. SADLER	12/12/2018	12.767	17.200	4.430	R	LABOR	TSE	U	12/12/2018	17.583
DONALD D. SADLER	12/13/2018	06.833	12.133	5.300	R	LABOR	TTE	U	12/13/2018	12.133
DONALD D. SADLER	12/13/2018	13.433	17.150	3.720	R	LABOR	TTE	A	12/13/2018	17.150
DONALD D. SADLER	12/14/2018	06.833	12.400	5.570	R	LABOR	TTE	A	12/14/2018	12.400
DONALD D. SADLER	12/14/2018	06.833	12.400	5.570	R	LABOR	TTE	A	12/14/2018	12.400
DONALD D. SADLER	12/14/2018	06.833	12.400	5.570	R	LABOR	TTE	D	12/14/2018	12.400
DONALD D. SADLER	12/14/2018	12.767	16.983	4.220	R	LABOR	TTE	U	12/14/2018	16.983
DONALD D. SADLER	12/17/2018	06.900	08.000	1.100	R	LABOR	TSE	U	12/17/2018	10.367
DONALD D. SADLER	12/17/2018	11.200	12.000	0.800	R	LABOR	TSE	A	12/17/2018	13.067
DONALD D. SADLER	12/17/2018	13.000	17.117	4.120	R	LABOR	TTE	A	12/17/2018	17.117
DONALD D. SADLER	12/18/2018	6.934	12.433	5.500	R	LABOR	TSE	U	12/18/2018	17.067
DONALD D. SADLER	12/18/2018	12.900	17.083	4.180	R	LABOR	TTE	A	12/18/2018	17.083
DONALD D. SADLER	12/19/2018	06.800	12.200	5.400	R	LABOR	TTE	A	12/19/2018	12.200
DONALD D. SADLER	12/19/2018	13.200	17.350	4.150	R	LABOR	TTE	A	12/19/2018	17.350
DONALD D. SADLER	12/31/2018	06.817	10.000	3.180	R	LABOR	TSE	U	12/31/2018	14.117
DONALD D. SADLER	01/02/2019	06.983	10.767	3.780	R	LABOR	TSE	U	01/02/2019	11.267
DONALD D. SADLER	01/02/2019	11.250	12.117	0.870	R	LABOR	TTE	U	01/02/2019	12.117
DONALD D. SADLER	01/02/2019	12.883	17.167	4.280	R	LABOR	TTE	A	01/02/2019	17.167
DONALD D. SADLER	01/03/2019	06.867	11.767	4.900	R	LABOR	TTE	A	01/03/2019	11.767
DONALD D. SADLER	BillAdjust			69.260		LABOR				

### PARTS

Parts Salesman: MP    Price Code: 2    Tax Code: 00    Sales Code: 04    Discount: 0

## Repair Order Review

### RITCHIE IMPL INC COBB

Part	Ven	Typ	Description	Ship QTY	BO QTY	Bin Location	Unit Price	Ext Price	Disc	PC	Tax	SC
0155500	297	1	WARNING BE	1	0	3D01	93.01	136.15	0	2	00	04
F0128770	845	1	SCREW	3	0	HWB02	0.36	1.08	0	2	00	04
19910090	297	1	V-RIBBED B	1	0	2G	45.48	72.65	0	2	00	04
1448980	297	1	V-BELT	1	0	2G	29.63	49.38	0	2	00	04
1426851	297	1	COVER	1	0		54.47	93.50	0	2	00	04
2368280	297	1	WASHER	3	0	2F05D	0.35	0.68	0	2	00	04
6066740	297	1	PIN	1	0	2F06F	7.90	13.17	0	2	00	04
1418691	297	1	SUPPORT	1	0		15.27	26.21	0	2	00	04
6016080	297	1	PIN	2	0	2F06F	7.90	13.17	0	2	00	04
2368280	297	1	WASHER	1	0	2F05D	0.35	0.68	0	2	00	04
2362000	297	1	BOLT/HEX	5	0	2F01A	0.16	0.30	0	2	00	04
9636680	297	1	BOLT/FLAT	2	0	HWA01D	0.70	1.33	0	2	00	04
2334230	297	1	SCREW	3	0	2F01A	0.68	1.29	0	2	00	04
2393931	297	1	WASHER/CON	11	0	HWA02A	0.12	0.23	0	2	00	04
2393931	297	1	WASHER/CON	4	0	HWA02A	0.12	0.23	0	2	00	04
1474721	297	1	AGRICOOOL	3	0	NAW3C	55.94	89.36	0	2	00	04
F0128758	845	1	SCREW	1	0	HWB02	0.23	0.69	0	2	00	04
MFC12P	800	1	REPELLENT	1	0	COUNTER	9.76	15.73	0	2	00	04
84090658	198	1	FUSE	1	0	2B06A	0.45	0.67	0	2	00	04
87693743	198	1	FUSE	1	0	2B06A	1.47	2.35	0	2	00	04
1428320	297	1	LOCK	1	0	2D04E	106.74	156.24	0	2	00	04
6979030	297	1	CAP/DUST	2	0	3D04	5.42	9.04	0	2	00	04
1102258	198	1	BULB	1	0	8A05D08	4.26	6.55	0	2	00	04
2159571	297	1	SWITCH	3	0	2C08D	26.60	44.33	0	2	00	04
2417931	297	1	EP3 GREASE	10	0	HWF04	3.31	5.53	0	2	00	04
ZQC5614051R	198	1	3/4 SHRINK	3	0	BATBOX1U&V1.20		1.60	0	2	00	04
ZQC812050R	198	1	2/0GA RED	1.500000	0	3G06C	6.71	8.95	0	2	00	04
ZQC486320005F	198	1	CLAMP	1	0	BATBOX3B	4.46	5.95	0	2	00	04
ZQC426320005P	198	1	CLAMP	1	0	BATBOX3S	6.30	8.40	0	2	00	04
ZQC426320005N	198	1	CLAMP	1	0	BATBOX3T	6.30	8.40	0	2	00	04
2334860	297	1	COACH BOLT	6	0	HWA01D	0.40	0.75	0	2	00	04
2382340	297	1	NUT/SECURE	1	0	HWA02E	0.45	0.85	0	2	00	04
2113250	297	1	PIN	1	0	2E05F	6.26	10.43	0	2	00	04
1234002	297	1	REAR PANEL	1	0	SP203B	108.67	163.81	0	2	00	04
F65080	845	1	COTTER PIN	3	0	HWB07	0.04	0.12	0	2	00	04
2334040	297	1	SCREW,HEX	1	0	2F01A	1.11	2.09	0	2	00	04
2351820	297	1	CIRCLIP152	2	0	2D05G	1.07	2.02	0	2	00	04
2155170	297	1	BEARING	2	0	2E10D	7.92	13.20	0	2	00	04
13122661	297	1	WHEEL CHOC	1	0	2E02A	152.88	223.78	0	2	00	04
6723662	297	1	TENSION PU	1	0	SP502C	171.83	259.02	0	2	00	04
13242220	297	1	POWER BAND	1	0	3G04	107.81	145.19	0	2	00	04
2336271	297	1	SHIM	2	0	2F04H	1.39	2.61	0	2	00	04
6012430	297	1	WASHER	1	0	2F06F	1.34	2.52	0	2	00	04
6088190	297	1	LOCK PIN	2	0	2F06F	11.56	19.26	0	2	00	04
F33024	845	1	WASHER	2	0	HWD08	0.52	1.56	0	2	00	04
7543183	297	1	BATTERY HO	1	0		18.65	32.00	0	2	00	04
19910001	297	1	FILTER ELE	2	0	3A	19.69	32.81	0	2	00	04
4843931	297	1	CONNECTING	1	0		68.17	102.77	0	2	00	04
1442300	297	1	FUEL FILTE	1	0	SP502C	270.71	379.74	0	2	00	04
5596460	297	1	POCKET FIL	2	0	SP201A	40.27	67.11	0	2	00	04
1442360	297	1	FILTER ELE	1	0	2C	54.71	91.18	0	2	00	04
1442310	297	1	CHANGEABLE	1	0	3B	66.61	111.02	0	2	00	04

## Repair Order Review

### RITCHIE IMPL INC COBB

0773821	297	1	FILTER,SAF	2	0	SP201C	94.86	138.85	0	2	00	04
1474830	297	1	10-40 OIL5	3	0	NAW4C	72.41	111.03	0	2	00	04
FREIGHTIN	965	1	FREIGHT IN	1	0	OFFICE	0.00	18.08	0	2	00	04
2375790	297	1	BOLT SUNK	4	0	2F03B	0.92	1.74	0	2	00	04
13180191	297	1	SHEARBAR	1	0	3E01	745.20	1045.35	0	2	00	04
13240930	297	1	WEAR PLATE	1	0	3E08A	52.47	87.46	0	2	00	04
13240920	297	1	WEAR PLATE	1	0	3E08A	52.47	87.46	0	2	00	04
2382681	297	1	SEAL RING	2	0	2D05A	1.93	3.63	0	2	00	04
2124321	297	1	SCREW PLUG	1	0		14.20	23.67	0	2	00	04
87299132	198	1	LIMIT SLIP	2	0	HWE03	49.22	58.60	0	2	00	04
2369012	297	1	SPRING PIN	2	0	2E05E	0.62	1.17	0	2	00	04
9538900	297	1	SHAFT	1	0	2D04D	84.70	123.98	0	2	00	04
F0128759	845	1	SCREW	2	0	HWB02	0.18	0.54	0	2	00	04
2343500	297	1	WASHER	2	0	2F06E	4.75	7.91	0	2	00	04
2114110	297	1	PIN/LYNCH	1	0	2C02G	1.84	3.47	0	2	00	04
1411630	297	1	PIN	1	0		39.42	67.67	0	2	00	04
F65149	845	1	PIN	4	0	HWB07	0.13	0.39	0	2	00	04
PPS316	800	1	CUTT OFF W	1	0	SERVICE	2.99	4.70	0	2	00	04
2393920	297	1	WASHER	1	0	HWA02A	0.08	0.16	0	2	00	04
1445931	297	1	GUARD	1	0	UPE06	0.05	75.56	0	2	00	04
2349530	297	1	BOLT/CARR	1	0	HWA01A	0.32	0.60	0	2	00	04
2373820	297	1	BOLT	4	0	2F01C	0.32	0.60	0	2	00	04
0779330	297	1	THRUST PIE	4	0	2B04C	14.97	25.69	0	2	00	04
1428581	297	1	BUSHING	2	0		12.23	20.38	0	2	00	04
1303140	297	1	COACH BOLT	3	0	HWA01E	3.35	6.31	0	2	00	04
2393931	297	1	WASHER/CON	3	0	HWA02A	0.12	0.23	0	2	00	04
2361700	297	1	NUT 8MM	3	0	HWA02C	0.10	0.18	0	2	00	04
1417970	297	1	LINER	1	0	LR1	150.00	202.00	0	2	00	04
1417743	297	1	WEAR PLATE	1	0	LR6	117.19	157.81	0	2	00	04
87299775	198	1	75W90 LUBE	1	0	HWE08	16.25	19.35	0	2	00	04
2188590	297	1	O-RING	1	0	2C06G	3.78	6.30	0	2	00	04
0689460	297	1	AERATION F	1	0	2E	206.84	302.77	0	2	00	04
1474450	297	1	HVLP 46 AG	2	0	NAW3C	58.21	89.26	0	2	00	04
15991770	297	1	FILTER ELE	1	0	2D	73.02	106.88	0	2	00	04
MC1270	198	1	PIPE TAPE	1	0	CARTD02	0.62	0.82	0	2	00	04
1474931	297	1	AGRISHIFT	1	0	NAW3A	35.69	52.62	0	2	00	04
0907673	297	1	HOSE	1	0	3G02C	8.38	13.97	0	2	00	04
2374420	297	1	BOLT 8X25	4	0	2F01A	0.16	0.30	0	2	00	04
2162670	297	1	NUT HEXAGO	1	0	2E06E	0.71	1.34	0	2	00	04
1474300	297	1	80W90 AGRI	1	0	NAW3C	65.32	100.15	0	2	00	04
2184170	297	1	O-RING	1	0	2C06C	0.46	0.86	0	2	00	04
2186970	297	1	O-RING	2	0	2C06E	1.03	1.95	0	2	00	04
2384080	297	1	O-RING	2	0	2C06F	2.30	4.34	0	2	00	04
2330000	297	1	HEXAGONAL	2	0	2F01C	1.35	2.55	0	2	00	04
4606210	297	1	BEARING SE	2	0	2D08G	5.01	8.35	0	2	00	04
2336920	297	1	BEARING GR	2	0	2F10B	8.93	14.88	0	2	00	04
2344330	297	1	SHIM	2	0	2F06D	1.19	2.25	0	2	00	04
2150480	297	1	BEARING	2	0	2E10D	13.30	21.85	0	2	00	04
2393870	297	1	WASHER/CON	4	0	HWA02A	0.65	1.22	0	2	00	04
2349570	297	1	SCREW/SOCK	3	0	2F03F	0.89	1.68	0	2	00	04
2361710	297	1	NUT 10MM	24	0	HWA02D	0.12	0.22	0	2	00	04
2393880	297	1	LOCKWASHER	24	0	HWA02B	0.14	0.27	0	2	00	04



## Repair Order Review

### RITCHIE IMPL INC COBB

2163961	297	1	COACH BOLT	24	0	2F02H	0.62	1.17	0	2	00	04
2401/0003	121	1	O-RING	1	0	FIP	0.52	0.79	0	2	00	04
1307021	297	1	PIPE	1	0	1E03C	30.99	53.19	0	2	00	04
2333300	297	1	UNION	1	0	2C05E	2.35	4.43	0	2	00	04
1307041	297	1	HYDR. PIPE	1	0	1E03C	36.01	61.81	0	2	00	04
2111840	297	1	UNION	1	0	2C05E	6.38	10.63	0	2	00	04
2381320	297	1	NUT/SECURE	2	0	HWA02C	0.32	0.60	0	2	00	04
2393880	297	1	LOCKWASHER	4	0	HWA02B	0.14	0.27	0	2	00	04
2381980	297	1	SHIM,WASHE	4	0	2F06D	5.47	9.12	0	2	00	04
2379470	297	1	NUT	4	0	HWA02D	0.37	0.69	0	2	00	04
2330610	297	1	WASHER	4	0	1C04C	2.08	3.93	0	2	00	04
1443550	297	1	CAP	1	0	1E03C	31.84	54.65	0	2	00	04
1445390	297	1	RING	1	0	2D02E	43.42	74.52	0	2	00	04
1474370	297	1	EP2 GREASE	1	0	HWF03	2.86	4.97	0	2	00	04
1238751	297	1	SCREW	4	0	2C11B	23.77	39.62	0	2	00	04
1238521	297	1	ANTIFRICTI	4	0	1C03C	5.28	8.80	0	2	00	04
1405221	297	1	GLIDE RAIL	2	0	1C03C	2.93	5.51	0	2	00	04
2361700	297	1	NUT 8MM	14	0	HWA02C	0.10	0.18	0	2	00	04
2339820	297	1	BOLT/SUNK	10	0	HWA01B	0.77	1.44	0	2	00	04
0763912	297	1	WEAR PLATE	1	0	3F08B	24.37	37.38	0	2	00	04
0763922	297	1	WEAR PLATE	1	0	3F08B	24.37	37.38	0	2	00	04
1233591	297	1	GUARD	1	0		30.33	52.06	0	2	00	04
1428541	297	1	ANGLE R.H.	1	0		81.46	122.80	0	2	00	04
2373830	297	1	BOLT10X25	4	0	2F01C	0.43	0.81	0	2	00	04
7450720	297	5	CORE	1	0	CORE	0.00	0.00	0	2	00	04
CORES:			Core Chrgs	1	0		0.00	505.00	0		00	04
7450710	297	3	MOTOR	1	0	CLBATT01	2883.68	4005.11	0	2	00	04
1445400	297	1	HOUSING	1	0	5E07	204.66	308.52	0	2	00	04
1445204	297	1	ACCELERATO	1	0	NBG2	1930.93	2881.98	0	2	00	04
2151900	297	1	BOLT/HEX	1	0	2F02B	3.01	5.67	0	2	00	04
2393910	297	1	WASHER/16M	1	0	HWA02B	1.09	2.03	0	2	00	04
6440190	297	1	TAPERED RI	2	0	2C02H	20.62	35.39	0	2	00	04
2393380	297	1	KEY	1	0	2E05H	2.88	5.42	0	2	00	04
2168910	297	1	SOCKET HEA	8	0	2F03D	0.25	0.47	0	2	00	04
2141320	297	1	SHAFT SEAL	1	0	1E03C	35.66	59.43	0	2	00	04
2351940	297	1	CIRCLIP	2	0	2D04H	6.13	10.22	0	2	00	04
2436330	297	1	ROLLER BEA	1	0	1E03C	134.20	196.45	0	2	00	04
1445380	297	1	RING	1	0	1E03C	59.66	99.43	0	2	00	04
1437920	297	1	BEARING UN	1	0	4C05B	338.43	495.38	0	2	00	04
2177700	297	1	COUNTERSUN	2	0	HWA01B	0.67	1.26	0	2	00	04
2393931	297	1	WASHER/CON	4	0	HWA02A	0.12	0.23	0	2	00	04
2393870	297	1	WASHER/CON	18	0	HWA02A	0.65	1.22	0	2	00	04
2387860	297	1	WASHER	2	0	2F05E	0.99	1.86	0	2	00	04
0677973	297	1	LEDGE	1	0	CLRACK2	35.16	53.91	0	2	00	04
1405112	297	1	SHAFT PLAT	1	0	CLRACK3	153.52	224.71	0	2	00	04
0786603	297	1	SHAFT PLAT	1	0	CLRACK3	75.94	102.26	0	2	00	04
0859300	297	1	CYLINDER H	1	0		51.55	88.48	0	2	00	04
2393941	297	1	WASHER/CON	4	0	HWA02A	0.34	0.64	0	2	00	04
1447310	297	1	GASKET	1	0	3E02A	34.55	57.58	0	2	00	04
2343250	297	1	WASHER	3	0	2F05E	0.10	0.18	0	2	00	04
2361700	297	1	NUT 8MM	9	0	HWA02C	0.10	0.18	0	2	00	04
2339820	297	1	BOLT/SUNK	9	0	HWA01B	0.77	1.44	0	2	00	04

## Repair Order Review

### RITCHIE IMPL INC COBB

2331950	297	1	WASHER	1	0	2F05E	0.77	1.44	0	2	00	04
2369132	297	1	WASHER	1	0	2F05D	0.06	0.12	0	2	00	04
2374530	297	1	BOLT10X30	6	0	2F01C	0.71	1.34	0	2	00	04
2378740	297	1	BOLT	4	0	2F01C	0.28	0.52	0	2	00	04
2393941	297	1	WASHER/CON	10	0	HWA02A	0.34	0.64	0	2	00	04
B505502	198	1	PENT OIL	1	0	12C	3.71	5.45	0	2	00	03
ZRG017BRC	198	1	BR-CLEANER	2	0	12C	3.40	5.00	0	2	00	03
07485	800	1	3w0022DISC	2	0	SERVICE	2.70	6.42	0	2	00	04
2388340	297	1	SEAL/RING	1	0	2C07E	7.67	12.78	0	2	00	04
0085430	297	1	BUSHING	3	0	2D01A	2.68	5.04	0	2	00	04
1231240	297	1	WEAR PLATE	1	0		1128.64	1583.23	0	2	00	04
2332800	297	1	BEARING GR	2	0	2E09D	31.84	53.07	0	2	00	04
2430640	297	1	CIRCLIP	1	0	2D10F	7.06	11.76	0	2	00	04
14124083	297	1	RETROFIT K	1	0	CLRACK1	2020.00	2885.71	0	2	00	04
7757930	297	1	CLUTCH PLA	1	0	12F05	900.81	1318.58	0	2	00	04
2351920	297	1	CIRCLIP	1	0	2D04C	3.53	5.88	0	2	00	04
2375970	297	1	CIRCLIP	1	0	2D05C	1.69	3.19	0	2	00	04
1309940	297	1	HUB	1	0	1C03B	178.68	269.35	0	2	00	04
1309091	297	1	GUIDE PULL	1	0		642.30	968.24	0	2	00	04
1410712	297	1	HOSE PIPE	2	0	3E03A	36.64	61.07	0	2	00	04
1246511	297	1	INSULATING	1	0	16D05	23.30	38.84	0	2	00	04
0689550	297	1	PROTECTOR	1	0		23.38	40.12	0	2	00	04
0118531	297	1	SWITCH ASS	1	0	2C08A	97.03	142.04	0	2	00	04
0118480	297	1	SWITCH KNO	1	0		4.38	7.30	0	2	00	04
1435933	297	1	LINEAR UNI	1	0	4C01	1176.44	1650.29	0	2	00	04
1418702	297	1	SUPPORT	1	0		14.92	25.61	0	2	00	04
RV	800	1	ANTIFREEZE	1	0	NAW2A	2.50	3.96	0	2	00	04

#### SUBLET

Code : OS      Description :      OUTSIDE LABOR/SUBLET      PD Number:1068.163  
 Cost : 125.00      Amount :      162.50      Tax Code : 00

#### OTHER

Code : WSD      Description :      WINTER SERVICE DISCOUNT      Tax Code : 00  
 Cost : -450.00      Qty :      1      Amount :

#### TOTAL

	Labor	Parts	Sublet	Other	Total
Customer Totals	13120.90	26170.17	162.50	-1742.11	37711.46